

DEPARTMENT OF TRANSPORTATION**DIVISION OF ENGINEERING SERVICES**

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch

690 Walnut Ave.St. 150

Vallejo, CA 94592-1133

(707) 649-5453

(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-007180**Date Inspected:** 04-Jun-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Chen Chih Ming**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Segments**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Dan Hernandez was present during the times noted above to observe the fit up, welding and related activities associated with the fabrication of the San Francisco Oakland Bay Self Anchored Suspension Bridge at Zhenhua Port Machinery Company (ZPMC) facility on Changxing Island.

OBG Assembly

Bay 13

Segment 8BW

This QA Inspector observed Flux Cored Arc Welding (FCAW) in progress of a Complete Joint Penetration (CJP) weld joint. The Weld joint is designated as SSD19-PP66-125. The welder is identified as #066163 and was observed welding in the 3G (vertical) position using approved Welding Procedure Specification WPS-B-T-2233-TC-U4b-F.

Segment 8AE

This QA Inspector observed Flux Cored Arc Welding (FCAW) in progress of a fillet weld joint. The Weld joint is designated as SSD15-PP61-063 to 102. The welder is identified as #037705 and was observed welding in the 3F (vertical) position using approved Welding Procedure Specification WPS-B-T-2133.

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

This QA Inspector observed Flux Cored Arc Welding (FCAW) in progress of a Complete Joint Penetration (CJP) weld joint. The Weld joint is designated as SEG044A-015. The welder is identified as #050242 and was observed welding in the 3G (vertical) position using approved Welding Procedure Specification WPS-B-T-2233-TC-U4b-F.

This QA Inspector observed Flux Cored Arc Welding (FCAW) in progress of a Complete Joint Penetration (CJP) weld joint. The Weld joint is designated as SEG044A-016. The welder is identified as #055491 and was observed welding in the 3G (vertical) position using approved Welding Procedure Specification WPS-B-T-2233-TC-U4b-F.

Bay 14

Segment 7CW

This QA Inspector observed Flux Cored Arc Welding (FCAW) in progress of a Complete Joint Penetration (CJP) weld joint. The Weld joint is designated as SEG037A-001. The welder is identified as #069866 and was observed welding in the 1G (flat) position using approved Welding Procedure Specification WPS-B-T-2231-B-U2-F.

Segment 7BW

This QA Inspector observed Flux Cored Arc Welding (FCAW) in progress of a Complete Joint Penetration (CJP) weld joint. The Weld joint is designated as SEG035-013 to 018. The welder is identified as #037907 and was observed welding in the 3G (vertical) position using approved Welding Procedure Specification WPS-B-T-2233-B-U2-F.

This QA Inspector observed Flux Cored Arc Welding (FCAW) in progress of a Complete Joint Penetration (CJP) weld joint. The Weld joint is designated as SEG035A-009. The welder is identified as #067275 and was observed welding in the 3G (vertical) position using approved Welding Procedure Specification WPS-B-T-2233-TC-U4b.

Segment 7AW

This QA Inspector observed Flux Cored Arc Welding (FCAW) in progress of a Complete Joint Penetration (CJP) weld joint. The Weld joint is designated as SSD13A-PP49-128, 134. The welder is identified as #066283 and was observed welding in the 3G (vertical) position using approved Welding Procedure Specification WPS-B-T-2233-TC-U4b-F.

Segment 6CW

This QA Inspector observed Flux Cored Arc Welding (FCAW) in progress of a Complete Joint Penetration (CJP) weld joint. The Weld joint is designated as SSD11-PP45-127, 133. The welder is identified as #201215 and was observed welding in the 3G (vertical) position using approved Welding Procedure Specification WPS-B-T-2233-TC-U4b-F.

ZPMC Quality Control (QC) Inspector is identified as Liu Ru Dan. QA Inspector observed QC Inspectors verify

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

welding parameters. The welding variables recorded by QC appeared to comply with the Applicable WPS.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No relevant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, 150-0042-2372 , who represents the Office of Structural Materials for your project.

Inspected By:	Hernandez,Dan	Quality Assurance Inspector
Reviewed By:	Carreon,Albert	QA Reviewer
